


DRAWING AT FULL SCALE, PLOT AT 0.1875000=1!!!



NOTE: DRIVE SHAFT LOCATION MAY  
BE ON EITHER CENTERLINE

CAD DRAWING

DTMN-420/52

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100

0001 100 4 100